## S.K STRUCTURAL CONSULTANTS



Regd No: 3-1053/PPA/19



## STRUCTURAL STABILITY CERTIFICATE

The recent inspection made by me on 19.02.2024, in the Educational Institutional Building of M/S "ACHARIYA BALA SIKSHA MANDIR" (Ground, First & Second Floors only) at R.S No; 72/2, 72/3, 72/4, 72/5, 72/6, 72/7, 72/8, 72/9, 73/1, 73/2, 73/3, 73/4, 73/5, 73/6, 74/4, 75/3, 75/4, in Fishing Harbour Road, Thengaithittu Revenue Village, Pondicherry Municipality, Puducherry.

I observed that the entire area of the "ACHARIYA BALA SIKSHA MANDIR" (Ground, First & Second Floors only) building is constructed in Reinforced Concrete Framed Structure. in the year of 2011-2012; wide Puducherry Planning Authority Plan Approval No: PPA/378/1668/Z(SB/2)/2011-12 dated: 16.03.2012.

The structural soundness of this existing building was verified by me with reference to IS:875 and IS:456-2000 and also as per relevant IS code of practices for Earthquake Resistance Structures (IS:4326-1993). I declare the building is structurally sound.

This structure is structurally sound enough and that it would be valid for03 (Three) yearsand will accommodate 2000 students.

Place: Puducherry Date: 28.03.2024

Dr. S. KANDASAMY,

S.K. STRUCTURAL CONSULTANTS
Regd No: 3-1053/PPA/19

D-14, Arul Oli Street, Vallalar Nagar, Nainarmandapam, Puducherry - 605 004.

Cell: 292551 0 8190965230